


Montageanleitung Sockel 0346, 100 mm hoch
Mounting Instructions for 100 mm High Base Type 0346
Instructions de Montage pour Socle Type 0346, Hauteur 100 mm

häwa 



DETAIL A


nachdem das Gewinde geformt ist
after the thread is formed
après que le fil soit formé

4Nm




DETAIL B

11 Nm



DETAIL C

11 Nm





häwa GmbH

häwa GmbH

Industriestraße 12
88489 Wain
Tel. 0 73 53 9 84 60
info@haewa.de
www.haewa.de

F 67600 Sélestat

häwa-France Sarl
22, Rue Roswag
Tel. +33 672 71 3309
info@haewa.fr

USA Duluth, GA 30097

häwa Corporation
3768 Peachtree Crest Drive
Tel. +1 770 9213272
info@haewa.com